

BRYAN'S SEPTIC SERVICE  
P.O. BOX 37  
WESTPORT, ONTARIO  
K0G 1X0  
(613) 273-3078

PUMPER REPORT  
SEPTIC SYSTEM MAINTENANCE  
& PUMPING INFORMATION

Name: @@@@@@@@@ Date: Aug 2-2016  
Address: 18 Sharon Fly Ln Phone: \_\_\_\_\_  
Location: West Deser / Lake

Type of Tank  One Compartment  Two Compartment  
Type of Tank  Septic Tank  Graywater  Aerobic  Other \_\_\_\_\_  
Approximate Capacity 600 gal  
Construction Materials  Concrete  Steel  Block  Fiberglass  Plastic  
 Other \_\_\_\_\_

**Initial Inspection**

Any part of the septic tank under deck, driveway, etc  Yes  No  
Any evidence of sewage seeping from the tank or lid  Yes  No  
Condition of top and lids  Good  Leaking  Needs Repair

**Before Pumping**

Condition of sewage in tank NORMAL  
Liquid level at the outlet invert  Above  Below  Normal

**After Pumping**

Condition of inlet baffle  Good  Needs Repair  Missing  
Condition of outlet baffle  Good  Needs Repair  Missing  
Evidence of water leakage: Into Tank  Yes  No From Tank  Yes  No

**Absorption System**

Type of Absorption System  Seepage Bed  Sand Mound  Sub-surface Sand Filter  
Flow Test  Yes  No Approximate Seepage at Bed 30 min good

**Comments**  
At time of pumping system working  
have some concern about tree around tile bed  
no problem yet but could be if tree are not  
cut back

*Bryan*